

Inspector: Flightlog: 10213

Date: 23.10.2024

Landings: 13569

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
05	Airframe Structure Modification for Camera installation	Installed per EO 101233		22.02.2002
05	Bendix/King RMI KI 229	Installed per MC ASE-12-027-01		17.12.2012
				8757
				10926
05	Garmin 430AW -COM/NAV1	Installed per EMZ RC/SA1122 and WAAS upgrade per MC ASE-09-001-01		02.03.2009
05	Garmin G500 - PFD/MFD	STC Change to 10053008 Rev. 2 - Installed per EASA STC 10031729	Changed 16.Jul.2024	17.12.2012
			10.186HRS / 13.518LDG	8757
				10926
05	Garmin GFC500 Auto Pilot	Installed per EASA STC 10069439 Revision 7		04.03.2024
				10139
				13431
05	Garmin GI275 - Standby ADI	Installed per EASA STC 10075142 R3		04.03.2024
				10139
				13431
05	Garmin GMA430P - Audio Panel	Installed per MC ASE-10-015-01		17.12.2012
				8757
				10926
05	Garmin GTX330 - Transponder	Installed per MC EASA.A.C.04066		30.03.2027
05	GPS Antenna Installation for photo mission usage	Installed per EO 4498/02		04.11.2004

Inspector: Flightlog: 10213

Date: 23.10.2024

Landings: 13569

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
05	Honeywell RDR200 - WX Radar	Installed per EO 0400-OE-FSM		20.02.2009
05	Kannad ELT 406AF	Installed per MC EASA 2005-5817		02.08.2005
05	Piper Weight Reduction 1.999kg	Performed via Kit 764-048		
05	Radome Installation	Installed per STC FAA SA50GL - Kit AD4011X-2-1		
22	Garmin GFC500 - GMC507	Installed per EASA STC 10069439 Revision 7	011-04548-01 5H1103370	04.03.2024 10139 13431
22	Garmin GFC500 - GSA28 w/ Ball Bearings - Pitch	Installed per EASA STC 10069439 Revision 7	011-02927-21 included in 010-01068-21 6N2015265	04.03.2024 10139 13431
22	Garmin GFC500 - GSA28 w/ Ball Bearings - Roll	Installed per EASA STC 10069439 Revision 7	011-02927-21 included in 010-01068-21 6N2005339	04.03.2024 10139 13431
22	Garmin GFC500 - GSA28 w/ Ball Bearings - Trim	Installed per EASA STC 10069439 Revision 7	011-02927-21 included in 010-01068-21 6N2010268	04.03.2024 10139 13431
22	Garmin GFC500 - Kit 0H, Pitch Trim Servo	Installed per EASA STC 10069439 Revision 7	K11-00024-0H NSN	04.03.2024 10139 13431

Inspector: Flightlog: 10213

Date: 23.10.2024

Landings: 13569

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
22	Garmin GFC500 - Kit56, 2 Servo	Installed per EASA STC 10069439 Revision 7	K11-00024-oG	04.03.2024
				10139
			NSN	13431
24	Battery		G 35	10.01.2024
				10136
			G03170795	13424
24	Master Switch		587-837	10.01.2024
				10136
			NSN	13424
25	Kannad 406AF - Connector, DIN12	Installed per MC EASA 2005-5817	S1820514-03	02.08.2005
			M1367-0158	
25	Kannad 406AF - ELT	Installed per MC EASA 2005-5817	S1821502-02	02.08.2005
			# P1273-0045	
25	Kannad 406AF - ELT Antenna	Installed per MC EASA 2005-5817	1327-82	02.08.2005
			# 3905	
25	Kannad 406AF - ELT Remote Control Panel RC100	Installed per MC EASA 2005-5817	S1820513-03	02.08.2005
			# 403246-0216	
25	Kannad 406AF - Mounting Bracket	Installed per MC EASA 2005-5817	S1820511-01	02.08.2005
			P1281-0224	
28	LH otbd Fuel Qty sensor	Replaced		27.06.2019
				9590

Inspector: Flightlog: 10213

Date: 23.10.2024

Landings: 13569

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
29	Hydraulic Power Pack		HYC-5005	22.07.2010
				8445
			# 4473 / AH-11561	10110
30	DEICE BOOT	LH WING	25S7D5036-07 / 553-604	02.06.2020
				9708
			# NBZ9520	12623
30	DEICE BOOT	VERT. STABILICER	25S7D5036-05	31.03.2000
				5520
			# ME 63990	5903
30	DEICE BOOT	LH ELEVATOR	25S7D5036-03	31.03.2000
				5520
			# MJ 73800	5903
30	DEICE BOOT	RH WING	25S7D5036-08	31.03.2000
				5520
			# 313 MR	5903
30	DEICE BOOT	RH ELEVATOR	25S7D5036-04	31.03.2000
				5520
			# MI 55380	5903
31	RH Tach Drive Adapter	Replaced	640925	13.12.2021
				9957
				13055
32	LH Brake Disc		164-21600	01.02.2022
				9968
			NSN	13076
32	LH Brake Lining		066-06200	05.12.2023
				10133
			NSN	13415

Inspector: Flightlog: 10213

Date: 23.10.2024

Landings: 13569

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
32	RH Brake Disc		164-21600	01.02.2022
				9968
			NSN	13076
32	RH Brake Lining		066-06200	05.12.2023
				10133
			NSN	13415
32	Tire MLG RH		606C86-6	01.02.2022
				9968
			91422371	13076
32	Tire MLG LH		606C86-6	31.05.2021
				9880
			11130151	12936
32	TIRE NLG		606C86-6	17.04.2018
				9374
			53322041	12103
34	ADF - Antenna	Mod Status 3	King KA - 44B	18.11.1996
			071-1234-01	
			# 19497	
34	ADF - Indicator	Mod Status 2	King KI - 227	18.11.1996
			066-3063-01	
			# 5203	
34	ADF - Receiver	Mod Status 1-5	King KR - 87	18.11.1996
			066-1072-00	
			# 22000	
34	Airspeed Indicator 1	Repaired by Kroneis	United Instr.	02.06.2020
			8125	9708
			# 81437	12623

Inspector: Flightlog: 10213

Date: 23.10.2024

Landings: 13569

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
34	Airspeed Indicator 2	Repaired by Kroneis	United Instr.	02.06.2020
			8125	9708
			# 98898	12623
34	Altimeter 1		Aero Mech	
			8140B - 20MB	
			# 9950	
34	Altimeter 2		United Instrument	
			5934PM - 3	
			# 7K728	
34	Att. Gyro Co - Pilot		AIM 305-2AL	07.07.1997
			5040033928	
			# 25023	
34	Bendix King KX165A - COM/NAV2		069-01033-0201	12.09.2024
				10206
			13567	13554
34	Bendix/King KI 229 - RMI	Installed per MC ASE-12-027-01	066-3038-00	17.12.2012
				8757
			# 2933	10926
34	DME	Mod Status 1-5	King KN - 62A	02.03.2009
			066-1068-01	
			# 27267	
34	Garmin G500 - GDC 74A HIRF	Installed per EASA STC 10031729 - STC Change to 10053008 Rev. 2	010-00336-10	17.12.2012
			011-00882-10 included	8757
			# 20613507	10926
34	Garmin G500 - GRS 77 HIRF	Installed per EASA STC 10031729 - STC Change to 10053008 Rev. 2	010-00295-10	17.12.2012
			011-00868-10 included	8757
			# 42021310	10926

Inspector: Flightlog: 10213

Date: 23.10.2024

Landings: 13569

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
34	Garmin G500 - GDU 620	Installed per EASA STC 10031729 - STC Change to 10053008 Rev. 2	010-00482-50	17.12.2012
			011-01264-50 included	8757
			# 185202433	10298
34	Garmin G500 - GTP59	Installed per EASA STC 10031729 - STC Change to 10053008 Rev. 2	011-00978-00	17.12.2012
				8757
			# 47920986	
34	Garmin G500 - SD Kart TRN/OBS/APT DB/SUPP/SAFETAX	Installed per EASA STC 10031729 - STC Change to 10053008 Rev. 2	010-00769-44	17.12.2012
				8757
			N/A	
34	Garmin G500 Installation - Garmin GMU44	Installed per EASA STC 10031729 - STC Change to 10053008 Rev. 2	010-00296-00	17.12.2012
			011-00870-00 included	8757
			# 47521019	10926
34	Garmin GI275 - ADI	Installed per EASA STC 10075142 R3	010-02326-10	04.03.2024
			includes 011-04489-10	10139
			5MZ117750	13431
34	Garmin GI275 - Battery Pack ADI	Installed per EASA STC 10075142 R3	010-02304-00	04.03.2024
				10139
			5MZ617714	13431
34	Garmin GI275 - GPS Antenna	Installed per EASA STC 10075142 R3	010-12444-10	04.03.2024
			includes 011-04036-10	10139
			641006944	13431
34	Garmin GI275 - GSB15	Installed per EASA STC 10075142 R3	010-02544-21	04.03.2024
			includes 011-04937-20	10139
			63M257040	13431
34	Garmin GMA430P - Audio Panel	Installed per MC ASE-10-015-01	010-00152-11	17.12.2012
			011-00401-10 included	8757
			# 96292673	10926

Inspector: Flightlog: 10213

Date: 23.10.2024

Landings: 13569

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
34	Garmin GNS430AW - COM/NAV 1	Installed per EMZ RC/SA1122 and WAAS upgrade per MC ASE-09-001-01	GNS 430 AW Mod 1-7	02.03.2009
			010-00413-01	8239
			# 23500439	9686
34	Garmin GNS430AW Installation - GA35 GPS Antenna	Installed per EMZ RC/SA1122 and WAAS upgrade per MC ASE-09-001-01	013-00235-00	12.07.2024
				10186
			233616	13518
34	Garmin GTX 330 - Transponder	Installed per MC EASA.A.C.04066	011-00455-00	30.03.2007
			# 84124975	
34	Garmin GTX330 Installation - Encoder	Installed per MC EASA.A.C.04066	SAE5-35	02.03.2009
			013-00066-00	
			# 7454	
34	GPS Antenna - Foto Flights	Installed per EO 4498/02	S67-1575-96	05.06.2002
			1977	
34	Honeywell ART2000 - WX Radar	Installed per EO 0400-OE-FSM	071-01519-0101	02.03.2009
			# 11769	
34	HSI Co - Pilot		King KI - 525 A	
			066-3046-00	
			# 9941	
34	MKR	Garmin	GMA 340	29.11.2012
			010-00152-11	
			# 96292673	
34	NAV - Indicator	Mod - Status 1,3,4	King KI - 204	30.04.1998
			# 52757	

Inspector: Flightlog: 10213

Date: 23.10.2024

Landings: 13569

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
34	Partial Cabin Refurbishment	Performed per EO 10155		20.09.2001
34	VOR / LOC Converter	Mod - Status 1,2,3	King KN-72 066-4009-00 # 29092	04.03.2003 6314
74	Spark Plugs	Replaced	RHM 38E	03.02.2016 9080
95	Attitude Gyro	Removed by GI275 Installation	23-501-06-16 5000B-36 # T63942K	04.03.2024 10139 13431
95	Autopilot	Removed by Garmin AP installation	KFC - 200 # 3385	04.03.2024 10138 13431
95	MFD KDM 850	Removed - RDR Function transferred to G500		04.03.2024 10139 13431
95	Servo - Roll	Removed by Garmin AP installation	King KS 271B 065-0028-01 # 6090	04.03.2024 10138 13431